



109 LATHE RPM CHART

1800 RPM Motor speed

BACK GEAR	BELT POSITION		
	3	2	1
A	290	188	135
B	1450	940	675